



**Important note:**

When your mobile functions correctly in combination with the CC 9050/51, it is not always required to install the latest available software update. Please note that a new software version does not necessarily entail new functions. Sometimes it only involves complements concerning the compatibility with mobile phones. If it is not possible to establish a connection, please check and if necessary, update the software release (firmware) of your mobile phone or hands-free car kit. If a Bluetooth connection is successfully established, but not all functions of the hands-free car kit are available or if you observe unusual behaviour of the car kit, also check and if necessary, update the software of your mobile phone or car kit.

**How do I update the CC 9050/51 operating system?**

**The most important steps are as follows:**

- 1.** You will need: a laptop, a Bluetooth stick (which you will connect to the laptop), Bluetooth administration software, CC 9050/51 Update Manager, and the latest CC 9050/51 software version.
- 2.** You will find the CC 9050/51 software plus Update Manager and the Bluetooth administration software BlueSoleil on our homepage / Comfort COMPACT 9050. Please download BlueSoleil and the latest CC 9050/51 software. Switch on the CC 9050/51 and wait until the display reads "disconnected".
- 3.** If you use BlueSoleil (otherwise analogue): Open the programme, search for Bluetooth devices in the menu "My Bluetooth" / "Bluetooth Device Discovery". The CC 9050/51 symbol appears on the laptop. Do not click on "Connect" yet!
- 4.** Initiate the update process at the CC 9050/51: Choose "Update" in the "Service" menu.
- 5.** To connect the CC 9050/51 to the laptop, doubleclick on the symbol for CC 9050/51 in the BlueSoleil software. Select the profile "Serial Bluetooth Interface". Enter 1234 (PIN code) in the window opened (on the laptop) for acknowledgement. You will now see a 'ray' between the symbol of the CC 9050/51 and the sun on the laptop. The CC 9050/51 displays the established connection via arrow symbols.
- 6.** On the laptop down to the right you will see the COM port assigned to the CC 9050/51 selected by the programme. Select this COM port under "Change Port" in the Update Manager.
- 7.** Click on "Update" in the Update Manager and have the update run.
- 8.** Then restart the CC 9050/51. Interrupt the power supply of the CC 9050/51 (ignition off) and re-establish it (ignition on). With ignition on, please wait for approx. 5 min until the update is completed and "Update OK" is displayed on the CC 9050/51.

The manufacturer cannot be held responsible for any malfunction to the unit caused by an incorrect software update procedure.

Subject to change. Errors and omissions excepted.