



No	Phone	Type	Profile	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
1	Nokia	3109c	HF	✓	✓	✓	✓	✓	Vp cp06w15_07w11
2		3110c	HF	✓	✓	✓	✓	✓	V04.91
3		3230	HF	✓	✓	✓	✓	✓	V3.0505.2
4		3250	HF	✓	✓	✓	✓	✓	V03.24
5		3650	HF	✓	✓	✓	✓	✓	V4.13
6		5200	HF	✓	✓	✓	✓	✓	V03.92
7		5300	HF	✓	✓	✓	✓	✓	V05.00
8		5500	HF	✓	✓	✓	✓	✓	V 03.18
9		5700	HF	✓	✓	✓	✓	✓	V 03.83.1
10		6103	HF	✓	✓	✓	✓	✓	V04.90
11		6021	HF	✓	✓	✓	✓	✓	V03.87
12		6110 Navigator	HF			✓	✓	✓	V03.58
13		6125	HF	✓	✓	✓	✓	✓	V03.71
14		6131	HF	✓		✓	✓	✓	V03.70
15		6151	HF	✓	✓	✓	✓	✓	V03.56
16		6230	HF	✓	✓	✓	✓	✓	V5.40
17		6230i	HF	✓	✓	✓	✓	✓	V3.30
18		6233	HF	✓	✓	✓	✓	✓	V03.70
19		6234	HF	✓	✓	✓	✓	✓	V3.50
20		6270	HF	✓	✓	✓	✓	✓	V3.66
21		6280	HF	✓	✓	✓	✓	✓	V4.25
22		6288	HF	✓	✓	✓	✓	✓	V05.92
23		6300	HF	✓	✓	✓	✓	✓	V 04.70
24		6310	HF	✓	✓	✓	✓	✓	V5.10
25		6310i	HF	✓	✓	✓	✓	✓	V5.51
26		6600	HF	✓	✓	✓	✓	✓	V3.42.1
27		6630	HF	✓	✓	✓	✓	✓	V2.39.152
28		6680	HF	✓	✓	✓	✓	✓	V3.04.11
29		6681	HF	✓	✓	✓	✓	✓	V3.10.6
30		6810	HF	✓	✓	✓	✓	✓	V03.30
31		6820	HF	✓	✓	✓	✓	✓	V04.25
32		6820a	HF	✓	✓	✓	✓	✓	
33		6822	HF	✓	✓	✓	✓	✓	V4.48
34		7370	HF	✓	✓	✓	✓	✓	V 04.17
35		7380	HF	✓	✓	✓	✓	✓	V03.80
36		7710	HF	✓	✓	✓	✓	✓	V03.04.2
37		8800	HF	✓	✓	✓	✓	✓	V03.60
38		8801	HF	✓	✓	✓	✓	✓	V03.94
39		8910	HF	✓	✓	✓	✓	✓	V04.02
40		9300	HF	✓	✓	✓	✓	✓	V4.53
41		9300i	HF	✓	✓	✓	✓	✓	V 05.50(00)
42		9500	HF	✓	✓	✓	✓	✓	V4.44
43		E50	HF	✓	✓	✓	✓	✓	V06.27.1.0
44		E60	HF	✓	✓	✓	✓	✓	V.0610.02.15
45		E61	HF	✓	✓	✓	✓	✓	V. 3.0633.09.04
46		E61i	HF	✓	✓	✓	✓	✓	V 1.0633.22.05
47		E65	HF	✓	✓	✓	✓	✓	V 1.0633.18.01
48		E70	HF	✓	✓	✓	✓	✓	V1.0610.05.06
49		E90	HF	✓	✓	✓	✓	✓	V07.24.0.3.0P
50		N70	HF	✓	✓	✓	✓	✓	V2.0536.02
51		N71	HF	✓	✓	✓	✓	✓	V 2.0613.1.12.1
52		N73	HF	✓	✓	✓	✓	✓	V2.0628.0.0.1
53		N76	HF	✓	✓	✓	✓	✓	V30.0.015
54		N80	HF	✓	✓	✓	✓	✓	V 3.0617.0.6
55		N90	HF	✓	✓	✓	✓	✓	V5.0607.7.3
56		N91	HF	✓	✓	✓	✓	✓	V1.11.003
57		N93	HF	✓	✓	✓	✓	✓	V10.0.025
		N93i	HF	✓	✓	✓	✓	✓	V11.0.009
58		N95	HF	✓	✓	✓	✓	✓	V11.0.026
59	N-GAGE	HF	✓	✓	✓	✓	✓	V3.30	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468\*, Faxline: (0) 1805 842 329\* \*(14ct/min),

E-mail: [infoline@bury.com](mailto:infoline@bury.com), Internet: [www.bury.com](http://www.bury.com)

✓ working



No	Phone	Type	Profile	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
60	Siemens	CX75	HF	✓	✓	✓		✓	SW:05
61		EL71	HF	✓	✓	✓		✓	SW:31
62		M75	HF	✓	✓	✓		✓	SW:05
63		S55	HF	✓	✓	✓	✓	✓	SW:91
64		S65	HF	✓	✓	✓		✓	SW:25
65		SK65	HF	✓	✓	✓		✓	SW:42
66		S65v	HF	✓	✓	✓		✓	SW:25
67		SP65	HF	✓	✓	✓		✓	
68		SX1	HF	✓	✓	✓	✓	✓	SW:14
69		SXG75	HF	✓	✓	✓		✓	W6250C-MMTO-1.4.33_3
70	Sony Ericsson	D750i	HF	✓	✓	✓	✓	✓	R1N035
71		K510i	HF	✓	✓	✓		✓	R4CH003
72		K530i	HF	✓	✓	✓	✓	✓	R6BC002
73		K550i	HF	✓	✓	✓	✓	✓	R1JD001
74		K600i	HF	✓	✓	✓	✓	✓	R2AC001
75		K610i	HF	✓	✓	✓	✓	✓	
76		K700i	HF	✓	✓	✓		✓	R2AY004
77		K750i	HF	✓	✓	✓	✓	✓	R1A0044
78		K800i	HF	✓	✓	✓	✓	✓	
79		K810i	HF	✓	✓	✓	✓	✓	R1JF001
80		M600i	HF	✓	✓	✓			R1B01
81		P800i	HS		✓				
82		P910i	HF	✓	✓	✓		✓	R4A006
83		P990i	HF	✓	✓	✓	✓		CXC162037 R7A001
84		S500i	HF	✓	✓	✓	✓	✓	R6BC002
85		S700i	HF	✓	✓	✓	✓	✓	R3C002
86		T68i	HF	✓	✓	✓	✓	✓	R5D007
87		T610	HF	✓	✓	✓	✓	✓	R3C002
88		T630	HF	✓	✓	✓	✓	✓	R7A011
89		T650i	HF	✓	✓	✓	✓	✓	R7AA024
90		W550i	HF	✓	✓	✓	✓	✓	R4BA041
91		W600i	HF	✓	✓	✓	✓	✓	R7B046
92		W610i	HF	✓	✓	✓	✓	✓	R1JD001
93		W660i	HF	✓	✓	✓	✓	✓	R6BC002
94		W700i	HF	✓	✓	✓	✓	✓	R1CA021
95		W800i	HF	✓	✓	✓	✓	✓	R1L002
96		W810i	HF	✓	✓	✓	✓	✓	R4DB005
97		W850i	HF	✓	✓	✓	✓	✓	R1ED001
98		W880i	HF	✓	✓	✓	✓	✓	R1JC002
99		W900i	HF	✓	✓	✓	✓	✓	R5BC004
100		W950i	HF	✓	✓	✓	✓	✓	R9C001
101		V630i	HF	✓	✓	✓	✓	✓	
102		V800	HF	✓	✓	✓	✓	✓	R1J002
103		Z520i	HF	✓	✓	✓		✓	R3F015
104		Z530i	HF	✓	✓	✓	✓	✓	R6BA030
105		Z600	HF	✓	✓	✓	✓	✓	RE004
106		Z610i	HF	✓	✓	✓	✓	✓	R1ED001
107		Z1010	HF	✓	✓	✓	✓	✓	RG007

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468\*, Faxline: (0) 1805 842 329\* \*(14ct/min),

E-mail: [infoline@bury.com](mailto:infoline@bury.com), Internet: [www.bury.com](http://www.bury.com)

✓ working



No	Phone	Type	Profile	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
108	<b>Motorola</b>	A 835	HF	✓	✓	✓	✓	✓	TALINT_0_7232.07.02P
109		C390	HF	✓	✓	✓	✓	✓	R368_G_0B_AQ0_05I
110		E1 ROKR	HF	✓	✓	✓	✓	✓	R373_G_0E.30.42R
111		E398	HF	✓	✓	✓	✓	✓	-
112		E770v	HF	✓	✓	✓	✓	✓	R25221_U85.83.E1P
113		E1070	HF	✓	✓	✓	✓	✓	R252211LD_U_85.97.C3P
114		KRZR K1	HF	✓	✓	✓	✓	✓	R4527_G_08.22.07R
115		KRZR K1m	HF	✓	✓	✓	✓	✓	24.1_00.25.0C
116		RIZR Z3	HF	✓	✓	✓	✓	✓	R452B_G_08.01.02R
117		L2 (v270)	HF	✓	✓	✓	✓	✓	R3511_G_0A.50.1BR
118		L6 (v280)	HF	✓	✓	✓	✓	✓	R3511_G_0A.50.22BR
119		L7	HF	✓	✓	✓	✓	✓	R4513_G_08.B7.54R_RB
120		MPx220	HF	✓	✓	✓	✓	✓	4.21.1088
121		RAZR V3x	HF	✓	✓	✓	✓	✓	R252211LD_U_85.92.70R
122		RAZR V3xx	HF	✓	✓	✓	✓	✓	R26111LD_U_96.67.32R
123		U6	HF	✓	✓	✓	✓	✓	R478_G_08.83.76R_A
124		W510	HF	✓	✓	✓	✓	✓	R452G_G_08..00.02I
125		V3i	HF	✓	✓	✓	✓	✓	R479_G_08.B4.85R
126		V3 RAZR	HF	✓	✓	✓	✓	✓	R374_G_0E40.3CR
127		V500	HF	✓	✓	✓	✓	✓	TRIPLETS_G_0B09.10R_VR
128	V525	HF	✓	✓	✓	✓	✓	TRIPLETS_G0B09.1DR_VR	
129	V550	HF	✓	✓	✓	✓	✓	R376_G_0E.65.26R	
130	V551	HF	✓	✓	✓	✓	✓	R47_G08_17.OFR01	
131	V600	HF	✓	✓	✓	✓	✓	TRIPLETS_G_0B09.38R	
132	V620	HF	✓	✓	✓	✓	✓	R376_G_0E.65.25R	
133	V635	HF	✓	✓	✓	✓	✓	R474_G_08.48.24R_A	
134	V80	HF	✓	✓	✓	✓	✓	R37_G_0E.03.26R	
135	<b>Toshiba</b>	TS921	HF	✓	✓	✓	✓	✓	
136		G500	HF	✓	✓	✓	✓	✓	
137	<b>Sharp</b>	GX15	HF	✓	✓	✓	✓	✓	
138		GX25	HF	✓	✓	✓	✓	✓	
139		GX30i	HF	✓	✓	✓	✓	✓	
140	<b>HP</b>	iPAQ6510 Voice Messenger	HF	✓	✓	✓	✓	✓	Version 5.2.1237(Build 17742.0.2.2)
141		iPAQ HW 6510	HF	✓	✓	✓	✓	✓	1.06.12 GER
142		iPAQ HW 6515	HF	✓	✓	✓	✓	✓	1.01.00 WWE
143		iPAQ HW 6915	HF	✓	✓	✓	✓	✓	1.47.00 GER
144	<b>Sda</b>	I	HF	✓	✓	✓	✓	✓	V4.21.1088
145		Music	HF	✓	✓	✓	✓	✓	
146		II	HF	✓	✓	✓	✓	✓	
147	<b>I-mate</b>	SP3i	HF	✓	✓	✓	✓	✓	
148		JAM	HF	✓	✓	✓	✓	✓	V 1.03.00
149	<b>SPV</b>	C-500	HF	✓	✓	✓	✓	✓	4.21.1088
150		C-700	HF	✓	✓	✓	✓	✓	1.06.00.00
151		M-500	HF	✓	✓	✓	✓	✓	1.05.10
152		M-1000	HS						1.10.00
153		M-2000	HF	✓	✓	✓	✓	✓	
154	<b>VPA</b>	Compact	HF	✓	✓	✓	✓	✓	1.05.00
155		III	HF	✓	✓	✓	✓	✓	
156	<b>MDA</b>	II	HS						4.20.0
157		Compact II	HF	✓	✓	✓	✓	✓	
158		Compact III	HF	✓	✓	✓	✓	✓	OS 5.1.342

BURY GmbH &amp; Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468\*, Faxline: (0) 1805 842 329\* \*(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com

✓ working



No	Phone	Type	Profile	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Access to mobile phone voice-dial function (voice tags)	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Version of phone software used to test/ Comments
159	<b>Samsung</b>	SCH-A930	HF	✓	✓	✓		✓	
160		SGH-D307	HF	✓	✓	✓	✓	✓	
161		SGH-D357	HF	✓	✓	✓	✓	✓	REV 1.4
162		SGH-D500	HF	✓	✓	✓		✓	
163		SGH-D520	HF	✓	✓	✓		✓	1.0c
164		SGH-D600	HF	✓	✓	✓		✓	
165		SGH-D840	HF	✓	✓	✓		✓	Rev 1.0a
166		SGH-D900	HF	✓	✓	✓		✓	D900E.05
167		SGH-E250	HF	✓	✓	✓		✓	LE250.09
168		SGH-E380	HF	✓	✓	✓		✓	FE380.02
169		SGH-E500	HF	✓	✓	✓	✓	✓	AE500.03
170		SGH-E720	HF	✓	✓	✓		✓	
171		SGH-F300	HF	✓	✓	✓		✓	Rev 1.1
172		SGH-U600	HF	✓	✓	✓		✓	Rev 0.2
173		SGH-U700v	HF	✓	✓	✓		✓	U700V.002
174		SGH-i600	HF	✓	✓	✓	✓	✓	FTA SW VERSION: i600.005
175		SGH-P900	HF	✓	✓	✓		✓	Rev 1.1
176	SGH-X820	HF	✓	✓	✓		✓	0.3b	
177	<b>Panasonic</b>	X70	HF	✓	✓			✓	
178	<b>Q-tek</b>	9090	HF	✓	✓	✓		✓	1.06.00
179		9100	HF	✓	✓	✓	✓	✓	1.6.7.1
180		2020	HS						1.14.00
181	<b>Xda</b>	Il s	HS	✓	✓	✓		✓	
182		Mini S	HF	✓	✓	✓	✓	✓	01.09.10
183	<b>BlackBerry</b>	7290	HF	✓	✓	✓		✓	V3.8.0.105
184		7100v	HF	✓	✓	✓		✓	V4.0.2.16
185		8100	HF	✓	✓	✓	✓	✓	V4.2.0.64
186		8120	HF	✓	✓	✓	✓	✓	V4.3.0.35
187		8300	HF	✓	✓	✓	✓	✓	OS 5.1.342
188		8700c	HF	✓	✓	✓		✓	V4.1.0.170
189		8700g	HF	✓	✓	✓		✓	V4.1.0258
190		8707v	HF	✓	✓	✓		✓	V4.1.0.316
191	8800	HF	✓	✓	✓	✓	✓	V4.2.1.43	
192	<b>Palm</b>	Treo 500V	HF	✓	✓	✓		✓	Radio Ver. V 3.1.6.P4_2007-08-01
193		Treo 650	HF	✓	✓	✓		✓	
183		Treo 680	HF	✓	✓	✓		✓	
184		Treo 750	HF	✓	✓	✓		✓	
185	<b>LG</b>	KG810	HF	✓	✓	✓		✓	
186		KG800	HF	✓	✓	✓		✓	
187	<b>HTC</b>	Breee (Bree 160)	HF	✓	✓	✓	✓	✓	Build 14928.2.2.0 Radio 0.90.00 RIL 2.002
188		Hermes	HF	✓	✓	✓	✓	✓	Build 14847.2.0.0 Radio 0.93.03
189		MTeor	HF	✓	✓	✓		✓	Build 14927.2.2.0 Radio 0.72.01
190		TyTN	HF	✓	✓	✓	✓	✓	Build 14954.2.3.0 Radio 0.96.00.00
191	<b>Apple</b>	iPhone	HF	✓	✓	✓		✓	1.0.2(1C28)

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468\*, Faxline: (0) 1805 842 329\* \*(14ct/min),

E-mail: [infoline@bury.com](mailto:infoline@bury.com), Internet: [www.bury.com](http://www.bury.com)

✓ working