

CC 9060 Email Read Patch for BlackBerry

The current version of the BURY e-mail read patch supports:

- One email account (the default email account).
- New incoming e-mails will be synchronised automatically with CC 9060.
- 30 e-mails per user (Oldest e-mail will be removed if new e-mail is received and 30 e-mails are already available).
- 2000 characters per e-mail will be synchronised.
(This means only a few lines of any email will be read aloud. Longer emails may not be read completely.)
- E-mail will be stored on the CC 9060 file system enabling the user to read old emails after ignition on and before next synchronisation (retrieving new emails).

Please read the following information carefully before proceeding:

- The patch only synchronises emails with the hands-free car kit if you use the **BlackBerry Internet Service**.
Other services such as the BlackBerry Enterprise Server for instance, are not supported.
- The BlackBerry Internet Service should be activated and the settings within the **Service Book** should be correct.
Tips about this are available at <http://de.blackberry.com/de> (german version) and <http://eu.blackberry.com/eng> (english version) or contact your network operator or service provider.
- Ensure your BURY CC 9060 Bluetooth car kit is running on **software v174 or later**.
- Check the software version on your BlackBerry handheld. The e-mail read patch may not work depending on this software version. How to find out which software version your handheld is using.
 1. Press in the menu key.
 2. Select in the menu item *Options*.
 3. Now select the menu item *About*.
 4. The software version is initially displayed. The 'platform version' is displayed in brackets.
- Handhelds which use:
Software ver. 4.6.x, 4.5.x 4.3.0 and 4.2.1 - your CC 9060 will read e-mails, get events (when new e-mail comes in you will be alerted with an icon on the CC 9060).
- E-mail text will only be shown as normal text. Text received in HTML format i.e. icons (smileys), text in bold, italics etc. will not be shown.
Message "Text format not supported" appears.
- Other software versions are not supported by the e-mail read patch.

To install the patch:

1. Select 'Browser' in the main menu **on your BlackBerry mobile**.
2. Press the option button and then 'Go to...'
3. Enter the web address: www.bury.com/blackberrypatch (open this link only from BlackBerry handheld web browser).
4. Highlight the filename: E-mailReadPatch.jad
5. Select 'Download'
6. If you have a previous version of the BURY e-mail read patch installed in your handheld, when installing the new one, the phone will ask you to replace it – answer yes.
7. After the file has been successfully downloaded, make a power reset on the handheld (turn off the handheld and remove the battery for a couple of seconds) this will ensure that the patch starts correctly in the background when the handheld is switched back on.

Important information

The email read feature of the CC 9060 is implemented to alert the user, that new emails have been received and to give a brief overview of the content of the email. If you require more details from the email, this should be done from the safety of your home or office and not whilst in the vehicle. The driver is ultimately responsible for the safe operation and control of their vehicle at all times. You should never use a hand held phone or smart device, including sending or reading text / picture messages and emails, while driving. Research indicates that there is a risk to safety when the driver of a motor vehicle is distracted and using a mobile phone while driving can be a distraction. The manufacturer strongly recommends that you use a hands-free solution when driving and, that you find a safe place to pull over and stop before making or taking a call.