



No	Phone	Type	Profile	Battery charge level	GSM-signal strength	service provider	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL-activation	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Call lists			Phone book entries		Messages		Version of phone software used to test/ Comments
											Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	
1	Nokia	3109c	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V cp06w15_07w15	
2	Nokia	3110c	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V 04.91	
3	Nokia	3250	HF				✓	✓	✓	✓	✓	✓	✓	✓			V 04.14	
4	Nokia	3650	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		V 4.17	
5	Nokia	5200	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V 03.92	
6	Nokia	5300	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V 05.51	
7	Nokia	5500d	HF				✓	✓	✓	✓	✓*	✓*	✓*	✓	✓*	✓*	V 04.03	
8	Nokia	5700	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓*	✓*	V 03.83.1	
9	Nokia	6021	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	V04.50	
10	Nokia	6103	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	V04.90	
11	Nokia	6111	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V 03.58	
12	Nokia	6120c	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V 04.21	
13	Nokia	6125	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V05.43	
14	Nokia	6131	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		V06.10	
15	Nokia	6151	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V04.10	
16	Nokia	6230	HF			✓	✓	✓	✓	✓	✓	✓	✓	✓			V 05.50	
17	Nokia	6233	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V 05.60	
18	Nokia	6234	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V03.38	
19	Nokia	6270	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V 03.69	
20	Nokia	6280	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V06.43	
21	Nokia	6288	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V06.10 new	
22	Nokia	6310i	HF			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	V5.52	
23	Nokia	6600	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V 5.53.0	
24	Nokia	6630	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V 6.03.08	
25	Nokia	6680	HF	✓*	✓*	✓*	✓	✓	✓	✓	✓*	✓*	✓				V5.04.07	
26	Nokia	6681	HF	✓*	✓*	✓*	✓	✓	✓	✓	✓*	✓*	✓*				V 6.09.00	
27	Nokia	6810	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	V 3.30	
28	Nokia	7370	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V04.13	
29	Nokia	7380	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	V 03.80	
30	Nokia	7710	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V 3.04.2	
31	Nokia	8600 Luna	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V 03.52	
32	Nokia	8800	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	V 04.10	
33	Nokia	8910	HF			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	V04.02	
34	Nokia	9300	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		V 05.22(01)	
35	Nokia	9300i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V 05.50(00)	
36	Nokia	E50	HF				✓	✓	✓	✓	✓*	✓*	✓*	✓*			V06.41.3.0	
37	Nokia	E60	HF				✓	✓	✓	✓	✓*	✓*	✓*	✓*			3.0633.09.04	
38	Nokia	E61	HF				✓	✓	✓	✓	✓*	✓*	✓*	✓*			2.0633.05.01	
39	Nokia	E61i	HF				✓	✓	✓	✓	✓*	✓*	✓*	✓*			V 2.0633.65.01	
40	Nokia	E65	HF				✓	✓	✓	✓	✓	✓	✓	✓	✓*	✓*	1.0633.58.02	
41	Nokia	E70	HF				✓	✓	✓	✓	✓*	✓*	✓*	✓*			3.0633.09.04	
42	Nokia	E90	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓*	✓*	V 07.24.0.3 OP	
43	Nokia	N70	HF				✓	✓*	✓*	✓	✓*	✓*	✓*	✓*			V 1.0610.05.07	
44	Nokia	N71	HF				✓	✓	✓	✓	✓*	✓*	✓*	✓*			V 4.0642.1.05	
45	Nokia	N73	HF				✓	✓*	✓*	✓*	✓*	✓*	✓*	✓*			V 3.0638.0.0.1	
46	Nokia	N76	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓*	✓*	V 31.0.014	
47	Nokia	N80	HF				✓	✓	✓	✓	✓*	✓*	✓*	✓*			V 4.0632.0.38	
48	Nokia	N90	HF				✓	✓	✓	✓	✓	✓	✓	✓	✓*	✓*	V 3.0607.7.3	
49	Nokia	N91	HF				✓	✓	✓	✓	✓*	✓*	✓*	✓	✓*	✓*	V 1.11.003	
50	Nokia	N93	HF				✓	✓	✓	✓	✓*	✓*	✓*	✓*	✓*	✓*	20.0.058	
51	Nokia	N95	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V12.0.013	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com

✓ working ✓* Phonebook and call list only from phone (with installed Applet)



No	Phone	Type	Profile	Battery charge level	GSM-signal strength	service provider	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Call lists			Phone book entries		Messages		Version of phone software used to test/ Comments
											Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	
52	Sony Ericsson	D750i	HF	✓	✓	✓	✓	✓	✓	✓ ²	✓	✓	✓	✓	✓	✓	✓	R1AA008 prgCXC125952_EU_1_CL
53	Sony Ericsson	K510i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R4CH003
54	Sony Ericsson	K550i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R1JD001 prgCXC1250669_GENERIC_LI
55	Sony Ericsson	K600i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R2AC001 prgCXC1250076_EU_6_MI
56	Sony Ericsson	K610i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R1JG001
57	Sony Ericsson	K800i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R1KG001
58	Sony Ericsson	K810i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R8BA024 prgCXC1250811_GENERIC_SM
59	Sony Ericsson	M600i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	PDA SW:CXC 162071 R6A16 Phone SW:CXC 162037 R9F011
60	Sony Ericsson	P910i	HF						✓	✓	✓	✓	✓					CXC162041 R2B01 040921
61	Sony Ericsson	P990i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	CXC162037 R7A001
62	Sony Ericsson	S700i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R3M008 prgCXC 125936_EU_2_T
63	Sony Ericsson	T610	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R6C005 prgCXC125665_EU_1
64	Sony Ericsson	T630	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R6C005 prgCXC125780_EU_2_N
65	Sony Ericsson	P1i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	CXC162037 R9G007
66	Sony Ericsson	T650i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R7AA024
67	Sony Ericsson	V800	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R1AF005 CXC125839_EU_1_VA
68	Sony Ericsson	W550i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R4CB020
69	Sony Ericsson	W580i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R6BC002
70	Sony Ericsson	W610i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R6BC002
71	Sony Ericsson	W660i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R8BB001
72	Sony Ericsson	W800i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R1BC002 prgCXC1250092_EU_1_CA
73	Sony Ericsson	W850i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R1JC002
74	Sony Ericsson	W880i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R8BA024
75	Sony Ericsson	W900i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R5BC004 prgCXC1250057_GENERIC_SA
76	Sony Ericsson	W950i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	CXC162058 R3A01
77	Sony Ericsson	Z530i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R6DA001
78	Sony Ericsson	Z600i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R2E004 prgCXC 12-6731_EU_7
79	Sony Ericsson	Z610i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R1ED001 prgCXC1250546_GEN ERIC_MY

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min),

E-mail: info@bury.com, Internet: www.bury.com

✓ working ✓* Phonebook and call list only from phone (with installed Applet)



No	Phone	Type	Profile	Battery charge level	GSM-signal strength	service provider	Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit / private mode with Bluetooth device / phones keys	Call lists			Phone book entries		Messages		Version of phone software used to test/ Comments
											Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	
80	Motorola	E1000	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			R26LD_U_83.39.24I
81	Motorola	E550	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			R376_G_0E.65.14R_A
82	Motorola	L2	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/R3511_G_0A.50.1BR
83	Motorola	L6	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	R3511_G_0A.50.22R
84	Motorola	U6	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			/R478_G_08.84.2DR_A
85	Motorola	RAZR V3	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/R374_G_0E.40.3CR
86	Motorola	RAZR V3c	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		R252211LD_U_85.97.43P
87	Motorola	V500	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			TRIPLETS_G_0B.08.8F5R
88	Motorola	V525	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			TRIPLETS_G_0B.09.1DR_VA
89	Motorola	V550	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			/R376_G_0E.65.26R
90	Motorola	V600	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			TRIPLETS_G_0B.09.38R
91	Motorola	V620	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			/R376_G_0E.65.25R
92	Motorola	V80	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			R37_G_0E.03.26R
93	Motorola	Z8	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			ESP00_U46.03E3G_0000053E
94	Samsung	SGH-D900	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	D900E.05
95	LG	KG810	HF				✓	✓	✓	✓	✓	✓	✓	✓	✓			KG810P64 EUR V10g Aug 18 2006
96	BlackBerry	7290	HF		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			v4.0.2.49 (Platform 1.8.0.142)
97	BlackBerry	7130	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			u4.1.0.317 (Platform 2.1.0.26)
98	BlackBerry	8100	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V4.2.0.51
99	BlackBerry	8300	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V 4.2.2.114
100	BlackBerry	8707	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V4.1.0.308
101	BlackBerry	8700c	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			v4.1.0.170 (Platform 2.0.0.79)
102	BlackBerry	8800	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			V4.2.1.43
103	HTC	SPV C-500	HF				✓	✓	✓	✓	✓	✓	✓	✓	✓			4.21.1088
104	HTC	SPV M-5000	HF				✓	✓	✓	✓	✓	✓	✓	✓	✓			OSS.1.1700(Build 14328.0.0.0)
105	SHARP	GX25	HF				✓	✓	✓	✓	✓	✓	✓	✓	✓			
106	SHARP	GX30i	HF				✓	✓	✓	✓	✓	✓	✓	✓	✓			A02-010-0041-GX30
107	Siemens	CX75	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	sw:17
108	Siemens	EL71	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	SW:31
109	Siemens	M75	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	SW:17
110	Siemens	S65	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	sw:11
111	Siemens	S75	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	SW:16
112	Siemens	SK65	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	SW:50
113	Siemens	SP65	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	SW:47

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com

✓ working ✓* Phonebook and call list only from phone (with installed Applet)