



No	Phone	Phone	Profile	Accept incoming call with device	Establish outgoing call with device	Phone book entries		Call lists			Battery charge level	GSM-signal strength	service provider	SMS reception	Version of phone software used to test/ Comments
						SIM Card	Phone	Received calls	Missed calls	Dialled numbers					
1	Motorola	V80	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R37_G_0E.05.26R	
2		V500	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ TRIPLETS_G_0B.08.8F5R	
3		V525	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ TRIPLETS_G_0B.09.1DR_VA	
4		V550	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R376_G_0E.65.26R	
5		V551	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R47_G_08.17.0FR_01	
6		V557	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4512_G_08.28.40R	
7		V600	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ TRIPLETS_G_0B.09.38R	
8		V620	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R376_G_0E.65.25R	
9		V635	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R474_G_08.48.24R_A	
10		L2	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R3511_G_0A.53.15R	
11		L6	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R3511_G_0A.50.22R	
12		L7	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4513_G_08.B7.5DR_RB	
13		V3	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R374_G_0E.40.79R	
14		V3c	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R479_G_08.B4.85R	
15		V3i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R479_G_08.B4.85R	
16		V3x	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R25221LD_U_85.97.43P	
17		V3xx	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 2611LD_U_96.80.56R	
18		K1	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4527_G08.22.07R	
19		K1mm	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 24.5_01.09.HA	
20		L7cm	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 24.5_01.11.HA	
21		U6	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R478_G_08.83.76R_A	
22		C390	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R368_G_0B.A0.0FR	
23		Z3	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4527_G08.01.02R	
24		1070	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R25221LD_U_85.97.C3P	
25		ROKR E1	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R373_G_0E.30.42R	
26		E550	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R376_G_0E.65.14R_A	
27		E770v	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R25221_U_85.83.E1P	
28		E815	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ E815_X_01.21.0R_HA	
29		E1000	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R26LD_U_83.39.24I	
30	Nokia	3109c	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ V cp06w15_07w15	
31		3110c	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ Vp sk4.80	
32		3230	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 3.0505.2	
33		3250	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.24	
34		5200	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.25	
35		5300	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 03.92	
36		5500d	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 4.03	
37		5700	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 03.27	
38		6021	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 04.90	
39		6085	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 03.71	
40		6103	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 04.90	
41		6110 Navi	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 03.51	
42		6111	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 03.58	
43		6125	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 03.71	
44		6131	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.70	
45		6151	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.56	
46		6230	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 05.24	
47		6230i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.88	
48		6233	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.70	
49		6234	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 4.91	
50		6270	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 03.66	
51		6280	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.65	
52		6288	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 5.92	
53		6300	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	v04.70	
54		6310	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 4.10	
55		6310i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 5.60	
56		6600	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 3.42.1	
57		6630	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 2.39.152	
58		6670	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 6.0522.0	
59		6680	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 2.04.15	
60		6681	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 3.10.6	
61		6682	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	/ 3.01.1	
62		6810	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.30	
63		6820a	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 4.25	
64		6822a	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 4.52	



working



Phonebook and call list only from phone (with installed Applet)



No	Phone	Phone	Profile	Accept incoming call with device	Establish outgoing call with device	Phone book entries		Call lists			Battery charge level	GSM-signal strength	service provider	SMS reception	Version of phone software used to test/ Comments
						SIM Card	Phone	Received calls	Missed calls	Dialled numbers					
65	Nokia	7280	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ 3.22	
66		7710	HF	✓	✓						✓	✓	✓	/ 3.04.2	
67		8800	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ 4.10	
68		8801	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ 3.94	
69		8910	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ 04.02.25	
70		9300	HF	✓	✓						✓	✓	✓	/ 5.22	
71		9300i	HF	✓	✓						✓	✓	✓	/ 5.50	
72		E50	HF	✓	✓									/ 06.41.3.0	
73		E60	HF	✓	✓									/ 2.0618.06.05	
74		E61	HF	✓	✓									/ 2.0618.06.05	
75		E61i	HF	✓	✓									/ 1.0633.22.05	
76		E65	HF	✓	✓									/ 1.0633.18.01	
77		E70	HF	✓	✓									/ 2.0618.07.10	
78		E90	HF	✓	✓							✓	✓	/ 07.24.0.3.OP	
79		N70	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	/ 5.0638.3.0.1	
80		N71	HF	✓	✓									/ 2.0613.1.12.1	
81		N73	HF	✓	✓									/ 2.0628.0.0.1	
82		N76	HF	✓	✓							✓	✓	/ 10.0.035	
83		N80-1	HF	✓	✓									/ 3.0617.0.6	
84		N90	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	/ 5.0607.7.3	
85		N91	HF	✓	✓									/ 1.11.003	
86		N93	HF	✓	✓									/ 10.0.025	
87		N93i	HF	✓	✓									/ 11.0.009	
88		N95	HF	✓	✓								✓	/ 10.0.018	
89		Sony-Ericsson	D750i	HF	✓	✓	✓	✓	✓	✓	✓	✓			/ R1AA008 PRG CXC125952_EU_1_CLR1AA008
90			K510i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4CH003 1250231_GENERIC_C0
91			K550i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1JA015 prg CXC1250669_GENERIC_LI
92			K600i	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ R2AC001 CXC1250076.EU.6_MI
93	K610i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1BA022 prgCXC1250536_V	
94	K700i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R2L001 prgCXC 125821_EU_1_C	
95	K750i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1C004 prgCXC 1250035_EU_2_CL	
96	K800i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1ED001	
97	K810i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1KC001	
98	M600i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1B01	
99	P800		HS	✓	✓										
100	P900		HS	✓	✓										
101	P990i		HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ R4F01 CXC162058	
102	S700i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R3C002 PRGCXC125936_EU_2_T	
103	T610i		HF	✓	✓						✓	✓	✓	/ R3C002	
104	T630i		HF	✓	✓						✓	✓	✓	/ R7A011	
105	V630i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1CE001	
106	V800		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ P1J002 prg CXC125839_EU_1_VA	
107	W550i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4BA041	
108	W600i		HF	✓	✓						✓	✓	✓	/ R7B046	
109	W800i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1L002 PRG CXC1250092_EU_1_CA R1L002	
110	W810i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4DB005 prg CXC1250320	
111	W850i		HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ R1ED001 PRGCXC1250201_Vodafone_CYR1E	
112	W880i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1JC002	
113	W900i		HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ R5BC004	
114	W950i		HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ R9C001 prg CXC162037	
115	Z530i		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R6BA030 PRG 1250454_GENERIC_MUR6BA030	
116	Z600		HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R2E004 CXC125731_EU_7	
117	Z610i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1ED001		
118	Z1010	HF	✓	✓	✓		✓	✓	✓	✓	✓		/ R1G007 PRG CXC125432_EU_1_V		

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com



working



Phonebook and call list only from phone (with installed Applet)



No	Phone	Phone	Profile	Accept incoming call with device	Establish outgoing call with device	Phone book entries		Call lists			Battery charge level	GSM-signal strength	service provider	SMS reception	Version of phone software used to test/ Comments
						SIM Card	Phone	Received calls	Missed calls	Dialled numbers					
119	Siemens	CX75	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ SW:17	
120		EL71	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:31	
121		M75	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:23	
122		S55	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:91	
123		S65	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW: 50	
124		S65v	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ SW:25	
125		S75	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:16	
126		SK65	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ SW:50	
127		SP 65	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ SW: 47	
128		SXG 75	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW: W6250C-MMTO-1.3.906T	
129		BenQ M81	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ SW:46	
130	BenQ S68	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ SW:23		
131	Samsung	A900	HF	✓	✓			✓	✓	✓	✓	✓		/ SW: 1.0g	
132		D307	HF	✓	✓									/ 06	
133		D357	HF	✓	✓	✓		✓	✓	✓		✓	✓	/ 1.4	
134		D500	HF	✓	✓									/ EG001.08	
135		D520	HF	✓	✓	✓						✓	✓	/ SW: 1.0C	
136		D600	HF	✓	✓									/ TG001.06	
137		D840	HF	✓	✓	✓	✓	✓	✓	✓		✓	✓	/ F:Rev1.0a	
138		D800	HF	✓	✓	✓		✓	✓	✓		✓	✓	/ 1.1	
139		D900	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ D900E.05	
140		E250	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ E250JHGB1	
141		E380	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ FE380.02	
142		E720	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ SW: 1.0g	
143		E900	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ 1.0a	
144		i600	HF	✓	✓									/ 5.1.342 (Build 15096.3.0.0) RV i600XAFI3	
145		P900	HF	✓	✓	✓		✓	✓	✓		✓	✓	/ Rev 1.1	
146		U600	HF	✓	✓	✓		✓	✓	✓		✓	✓	/ ver:REV 0.2	
147		X820	HF	✓	✓	✓		✓	✓	✓		✓	✓	/ Rev. 0.3b	
148		Z230	HF	✓	✓									/ Z230JHFL2	
149		Z240	HF	✓	✓									/ Z240AIGC6	
150	Z370	HF	✓	✓						✓		✓	/ Z370JIGD4		
151	BlackBerry	7100	HF	✓	✓							✓		/ 4.02.16	
152		7130	HF	✓	✓									/ 4.10.327	
153		8100	HF	✓	✓		✓				✓	✓	✓	/ 4.2.0..51 (Platform 2.2.0.32)	
154		8707	HF	✓	✓	✓					✓	✓	✓	/ 4.1.0.275	
155	HTC	MDA	HF	✓	✓	✓		✓	✓	✓					
156		Xda Trion	HF	✓	✓	✓		✓	✓	✓				/ 1.25.207.1	
157		TyTN	HF	✓	✓	✓		✓	✓	✓				/ 0.93.03	
158		MDA II	HS	✓	✓									/ 1.72.01GER	
159		SPV C700	HS	✓	✓	✓	✓	✓	✓	✓				/ OS 5.1.195 (Build 14955.2.3.0)	
160	LG	KE850 PRADA	HF	✓	✓	✓	✓				✓	✓	✓	/ KE850P40-EUR-V10n-XXX-XX	
161		KG800	HF	✓	✓										
162		KG810	HF	✓	✓										
163		KP800 (8000)	HF	✓	✓									/ PX80PC06	
164	SHARP	GX15	HF	✓	✓									/ A07-0070210	
165		GX25 GZ200	HF	✓	✓										
166		GX30i	HF	✓	✓									/ A02-010-0041	
167	PalmOne	Treo 650	HF	✓	✓			✓	✓	✓	✓	✓		/ TREO650-1.02-CNG Firmware:1.51	
168		Treo 680	HF	✓	✓			✓	✓	✓	✓	✓		/ TREO-680-1.00A/3102-	
169		Treo 700p	HF	✓	✓			✓	✓	✓	✓	✓		/ 2106/105	
170		Treo 750v	HF	✓	✓			✓	✓	✓	✓	✓	✓		/ TREO750-1.14-VFD

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com



working



Phonebook and call list only from phone (with installed Applet)