



No	Phone	Phone	Profile	Accept incoming call with device	Establish outgoing call with device	Phone book entries		Call lists			Battery charge level	GSM-signal strength	service provider	SMS reception	Version of phone software used to test/ Comments
						SIM Card	Phone	Received calls	Missed calls	Dialled numbers					
1	Motorola	V80	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R37_G_0E.05.26R	
2		V500	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ TRIPLETS_G_0B.08.8F5R	
3		V525	HF	✓	✓					✓		✓		/ TRIPLETS_G_0B.09.1DR_VA	
4		V550	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ R376_G_0E.65.26R	
5		V551	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ R47_G_08.17.0FR_01	
6		V557	HF	✓	✓						✓		✓	/ R4512_G_08.28.40R	
7		V600	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ TRIPLETS_G_0B.09.38R
8		V620	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R376_G_0E.65.25R
9		V635	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R474_G_08.48.24R_A
10		L2	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R3511_G_0A.53.15R
11		L6	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R3511_G_0A.50.22R
12		L7	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R4513_G_08.B7.5DR_RB
13		V3	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R374_G_0E.40.79R
14		V3c	HF	✓	✓		✓	✓	✓	✓	✓	✓			/ R479_G_08.B4.85R
15		V3i	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R479_G_08.B4.85R
16		V3x	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R25221LD_U_85.97.43P
17		V3xx	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 2611LD_U_96.80.56R
18		K1	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R4527_G08.22.07R
19		K1mm	HF	✓	✓		✓	✓	✓	✓	✓				/ 24.5_01.09.HA
20		L7cm	HF	✓	✓		✓	✓	✓	✓	✓				/ 24.5_01.11.HA
21		U6	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R478_G_08.83.76R_A
22		C390	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R368_G_0B.A0.0FR
23		Z3	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R4527_G08.01.02R
24		1070	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R25221LD_U_85.97.C3P
25		ROKR E1	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R373_G_0E.65.14R_A
26		E550	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R376_G_0E.65.14R_A
27		E770v	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R25221_U_85.83.E1P
28		E815	HF	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	/ E815_X_01.21.0R_HA
29		E1000	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ R26LD_U_83.39.24I
30	Nokia	3109c	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ V cp06w15_07w15	
31		3110c	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ Vp sk4.80
32		3230	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	✓	/ 3.0505.2
33		3250	HF	✓	✓										/ 3.24
34		5200	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ 3.25
35		5300	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		/ 03.92
36		5500d	HF	✓	✓										/ 4.03
37		5700	HF	✓	✓						✓	✓			/ 03.27
38		6021	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 04.90
39		6085	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 03.71
40		6103	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 04.90
41		6110 Naví	HF	✓	✓										/ 03.51
42		6111	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 03.58
43		6125	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 03.71
44		6131	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 3.70
45		6151	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 3.56
46		6230	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 05.24
47		6230i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.88
48		6233	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 3.70
49		6234	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 4.91
50		6270	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 03.66
51		6280	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 3.65
52		6288	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 5.92
53		6300	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	v04.70
54		6310	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 4.10
55		6310i	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	/ 5.60
56		6600	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	✓	/ 3.42.1
57		6630	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	✓	/ 2.39.152
58		6670	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	✓	/ 6.0522.0
59		6680	HF	✓	✓	✓*	✓	✓	✓	✓	✓	✓	✓	✓	/ 2.04.15
60		6681	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	✓	/ 3.10.6
61		6682	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	✓	/ 3.01.1
62		6810	HF	✓	✓						✓	✓	✓	✓	/ 3.30
63		6820a	HF	✓	✓						✓	✓	✓	✓	/ 4.25
64	6822a	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ 4.52	





No	Phone	Phone	Profile	Accept incoming call with device	Establish outgoing call with device	Phone book entries		Call lists			Battery charge level	GSM-signal strength	service provider	SMS reception	Version of phone software used to test/ Comments
						SIM Card	Phone	Received calls	Missed calls	Dialled numbers					
65	Nokia	7280	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ 3.22	
66		7710	HF	✓	✓						✓	✓	✓	/ 3.04.2	
67		8800	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ 4.10	
68		8801	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ 3.94	
69		8910	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ 04.02.25	
70		9300	HF	✓	✓						✓	✓	✓	/ 5.22	
71		9300i	HF	✓	✓						✓	✓	✓	/ 5.50	
72		E50	HF	✓	✓									/ 06.41.3.0	
73		E60	HF	✓	✓									/ 2.0618.06.05	
74		E61	HF	✓	✓									/ 2.0618.06.05	
75		E61i	HF	✓	✓									/ 1.0633.22.05	
76		E65	HF	✓	✓									/ 1.0633.18.01	
77		E70	HF	✓	✓									/ 2.0618.07.10	
78		E90	HF	✓	✓							✓	✓	/ 07.24.0.3.OP	
79		N70	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	/ 5.0638.3.0.1	
80		N71	HF	✓	✓									/ 2.0613.1.12.1	
81		N73	HF	✓	✓									/ 2.0628.0.0.1	
82		N76	HF	✓	✓							✓	✓	/ 10.0.035	
83		N80-1	HF	✓	✓									/ 3.0617.0.6	
84		N90	HF	✓	✓	✓*		✓	✓	✓	✓	✓	✓	/ 5.0607.7.3	
85		N91	HF	✓	✓									/ 1.11.003	
86		N93	HF	✓	✓									/ 10.0.025	
87		N93i	HF	✓	✓									/ 11.0.009	
88		N95	HF	✓	✓								✓	/ 10.0.018	
89	Sony-Ericsson	D750i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1AA008 PRG CXC125952_EU_1_CLR1AA008	
90		K510i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4CH003 1250231_GENERIC_C0	
91		K550i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1JA015 prg CXC1250669_GENERIC_LI	
92		K600i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R2AC001 CXC1250076_EU.6_MI	
93		K610i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1BA022 prgCXC1250536_V	
94		K700i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R2L001 prgCXC 125821_EU_1_C	
95		K750i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1C004 prgCXC 1250035_EU_2_CL	
96		K800i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1ED001	
97		K810i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1KC001	
98		M600i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1B01	
99		P800	HS	✓	✓										
100		P900	HS	✓	✓										
101		P990i	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ R4F01 CXC162058	
102		S700i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R3C002 PRGCXC125936_EU_2_T	
103		T610i	HF	✓	✓						✓	✓	✓	/ R3C002	
104		T630i	HF	✓	✓						✓	✓	✓	/ R7A011	
105		V630i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1CE001	
106		V800	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ P1J002 prg CXC125839_EU_1_VA	
107		W550i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4BA041	
108		W600i	HF	✓	✓						✓	✓	✓	/ R7B046	
109		W800i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1L002 PRG CXC1250092_EU_1_CA R1L002	
110		W810i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R4DB005 prg CXC1250320	
111		W850i	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ R1ED001 PRGCXC1250201_Vodafone_CVR1E	
112		W880i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1JC002	
113		W900i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R5BC004	
114		W950i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R9C001 prg CXC162037	
115		Z530i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R6BA030 PRG 1250454_GENERIC_MUR6BA030	
116		Z600	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R2E004 CXC125731_EU_7	
117		Z610i	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1ED001	
118		Z1010	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ R1G007 PRG CXC125432_EU_1_V	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com



working



Phonebook and call list only from phone (with installed Applet)



No	Phone	Phone	Profile	Accept incoming call with device	Establish outgoing call with device	Phone book entries		Call lists			Battery charge level	GSM-signal strength	service provider	SMS reception	Version of phone software used to test/ Comments
						SIM Card	Phone	Received calls	Missed calls	Dialled numbers					
119	Siemens	CX75	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ SW:17	
120		EL71	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:31	
121		M75	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:23	
122		S55	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:91	
123		S65	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW: 50	
124		S65v	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ SW:25	
125		S75	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:16	
126		SK65	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ SW:50	
127		SP 65	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ SW: 47	
128		SXG 75	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW: W6250C-MMTO-1.3.906T	
129		BenQ M81	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:46	
130		BenQ S68	HF	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	/ SW:23	
131	Samsung	A900	HF	✓	✓			✓	✓	✓	✓	✓		/ SW: 1.0g	
132		D307	HF	✓	✓									/ 06	
133		D357	HF	✓	✓	✓		✓	✓	✓		✓	✓	/ 1.4	
134		D500	HF	✓	✓									/ EG001.08	
135		D520	HF	✓	✓	✓						✓	✓	/ SW: 1.0C	
136		D600	HF	✓	✓									/ TG001.06	
137		D840	HF	✓	✓	✓	✓	✓	✓	✓		✓	✓	/ F:Rev1.0a	
138		D800	HF	✓	✓	✓		✓	✓	✓		✓	✓	/ 1.1	
139		D900	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ D900E.05	
140		E250	HF	✓	✓	✓	✓	✓	✓	✓		✓	✓	/ E250JHGB1	
141		E380	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ FE380.02	
142		E720	HF	✓	✓	✓		✓	✓	✓	✓	✓	✓	/ SW: 1.0g	
143		E900	HF	✓	✓	✓		✓	✓	✓		✓	✓	/ 1.0a	
144		i600	HF	✓	✓									/ 5.1.342 (Build 15096.3.0.0) RV i600XAF13	
145		P900	HF	✓	✓	✓		✓	✓	✓		✓	✓	/ Rev 1.1	
146		U600	HF	✓	✓	✓		✓	✓	✓		✓	✓	/ ver:REV 0.2	
147		X820	HF	✓	✓	✓		✓	✓	✓		✓	✓	/ Rev. 0.3b	
148		Z230	HF	✓	✓									/ Z230JHFL2	
149		Z240	HF	✓	✓									/ Z240AIGC6	
150	Z370	HF	✓	✓						✓		✓	/ Z370JIGD4		
151	BlackBerry	7100	HF	✓	✓							✓		/ 4.02.16	
152		7130	HF	✓	✓									/ 4.10.327	
153		8100	HF	✓	✓						✓	✓	✓	/ 4.2.0..51 (Platform 2.2.0.32)	
154		8707	HF	✓	✓	✓					✓	✓	✓	/ 4.1.0.275	
155	HTC	MDA	HF	✓	✓	✓		✓	✓	✓					
156		Xda Trion	HF	✓	✓	✓		✓	✓	✓				/ 1.25.207.1	
157		TyTN	HF	✓	✓	✓		✓	✓	✓				/ 0.93.03	
158		MDA II	HS	✓	✓									/ 1.72.01GER	
159		SPV C700	HS	✓	✓	✓	✓	✓	✓	✓				/ OS 5.1.195 (Build 14955.2.3.0)	
160	LG	KE850 PRADA	HF	✓	✓	✓	✓				✓	✓	✓	/ KE850P40-EUR-V10n-XXX-XX	
161		KG800	HF	✓	✓										
162		KG810	HF	✓	✓										
163		KP800 (8000)	HF	✓	✓									/ PX80PC06	
164	SHARP	GX15	HF	✓	✓									/ A07-0070210	
165		GX25 GZ200	HF	✓	✓										
166		GX30i	HF	✓	✓									/ A02-010-0041	
167	PalmOne	Treo 650	HF	✓	✓			✓	✓	✓	✓	✓		/ TREO650-1.02-CNG Firmware:1.51	
168		Treo 680	HF	✓	✓			✓	✓	✓	✓	✓		/ TREO-680-1.00A/3102-	
169		Treo 700p	HF	✓	✓			✓	✓	✓	✓	✓		/ 2106/105	
170		Treo 750v	HF	✓	✓			✓	✓	✓	✓	✓		/ TREO750-1.14-VFD	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 1805 842 468*, Faxline: (0) 1805 842 329* *(14ct/min),

E-mail: infoline@bury.com, Internet: www.bury.com



working



Phonebook and call list only from phone (with installed Applet)